

Each system has been tested before shipping, however, should for any reason this system be found defective, do not repair. Report any shipping damage to carrier immediately. Request from your supplier instructions for replacement of damaged or defective equipment.

## **EZY-STIK II**

MARK AND DRILL HOLE  
FOR 1/4" MOUNT BOLT

MARK AND DRILL HOLE  
FOR 1/4" MOUNT BOLT

MARK AND DRILL HOLE  
FOR 1" STEERING SHAFT

**CUSTOMER SERVICE**  
**1-800-874-7861**

# **MOUNTING PATTERN**

## **MODEL 840**

MARK AND DRILL HOLE  
FOR 1/4" MOUNT BOLT

MARK AND DRILL HOLE  
FOR 1/4" MOUNT BOLT

## **IMPORTANT!**

Print using **NO SCALING**.

If not printed at **full actual size**, the template will not match the helm size and holes will not be drilled correctly.